

Appendix B- Emergency Work Versus Planned Work

Table 1 - Water main breaks occurred per year (2014 to 2018)

Watermain Statistics	2014	2015	2016	2017	2018	Average
Main Leaks Repaired (#)	182	72	81	377	329	208
Note: Regina has experienced a record number of water main breaks in 2017 and 2018.						

Table 2 - Planned Connections and Hydrant Replacements per year (2014 to 2018)

Year	Connection Replacements (Lead, Poly B and other Materials)	Hydrant Replacements	Total
2014	198	14	212
2015	78	12	90
2016	99	27	126
2017	87	20	107
2018	65	30	95
Average			126
Note 1: Infill connections were not considered in the stats since related reinstatement work is performed by contractors. Only connection replacements and hydrants replacements were considered since most of the reinstatement work is typically undertaken by City of Regina crews.			
Note 2: All connection replacements result in sidewalk excavations.			