

Appendix C-2

ELIGIBLE WORK ITEMS 2326 College Avenue	ESTIMATED COST
Replacement of deteriorating brick foundation including: (a) Remove, salvage clean and store existing brick base – prepare for re-installation (b) Demolish existing sun room for foundation repair and return to original 1912 covered veranda design (c) Excavate/demolish existing brick foundation and replace with proper foundation structure and support (d) Update mechanical and electrical distribution/insulate basement and update as per code (e) Reinstall salvaged brick and stone cap as per original, reestablish design elements such as the patio, covered veranda and return exterior elements (1 door and 1 window) to original design	
TOTAL ESTIMATE OF ELIGIBLE COSTS	\$349,197.41